

**Illinois Commerce Commission  
Pipeline Safety  
Exit Meeting Documentation Form**

<b>Operator:</b>	AMEREN ILLINOIS COMPANY
<b>Inspection Unit(s):</b>	Quincy/Pittsfield
<b>Date of Meeting:</b>	10/30/2014
<b>Pipeline Safety Analyst:</b>	Kevin Hecker
<b>Exit Meeting Contact:</b>	Chris Juliusson

**Exit Statement**

**INSPECTION FINDINGS**

**Standard Inspection - Field Audit**

**Issues(s) Found:**

**Code Part [192.353(a)]** - The bottom of the meter set at 1219 S. Charles Drive E. was buried. Staff requested that the meter set be raised.

**Code Part [192.481(c)]** - Staff observed a bolted flange at the soil to air interface behind Quincy Christian School. It appeared the school paved around this flange which could potentially trap moisture, ultimately causing corrosion. Existing corrosion observed is beyond light surface oxidation.

**Notice Of Amendment(s) Found:**

[NO NOAS FOUND]

**Notice Of Violation(s) Found:**

[NO NOPVS FOUND]

**Standard Inspection - Record Audit**

**Issues(s) Found:**

[NO ISSUES FOUND]

**Notice Of Amendment(s) Found:**

[NO NOAS FOUND]

**Notice Of Violation(s) Found:**

[NO NOPVS FOUND]

**PAST INSPECTION FINDINGS**

**Issue(s) Corrected:**

[NO ISSUES CORRECTED]


**Notice Of Amendment(s) Corrected:**

[NO NOAS CORRECTED]

**Notice of Violations(s) Corrected:**

[NO NOPVS CORRECTED]

Pipeline Safety Analyst Signature:



Operator Representative Signature:



---